



REMOTE² software history

Remote² 10001361 2.24

Date	Remote ² 10001361
21-12-2016	2.24 (A24) <ul style="list-style-type: none">• Robot can now keep gas signal active and at the same time send welding start signal.
14-04-2016	2.23 (A23) <ul style="list-style-type: none">• Version number change only.
14-12-2015	2.22 (A22) <ul style="list-style-type: none">• Bugfix: Error messages are not shown properly on the remote. This only applies for the remote and not Galaxy BOX.
01-12-2015	2.21 (A21) <ul style="list-style-type: none">• If an error was repetitive (came to often), the error screen could halt the software• Problem with reading data from Lexar SD cards is fixed• Possible to dump the data file from Galaxy Remote (for debug use)• If CAN communication, between Galaxy and DSP, can not be established, then error E11-44 is shown. E11-44 therefore replaces E02-04 regarding start up communication failure. E02-04 is still shown if the established connection is lost.
03-11-2015	2.20 (A20) <ul style="list-style-type: none">• Version code changed just to match 10001341 V3,20.
27-10-2015	2.19 (A19) <ul style="list-style-type: none">• It is now possible to save the system LOG on to an external SD card.
14-07-2015	2.18 (A18) <ul style="list-style-type: none">• Water pump would not start if you had entered the service menu first. This problem is fixed.
11-06-2015	2.17 <ul style="list-style-type: none">• Cable compensation is implemented.
27-05-2015	2.16

REMOTE² software history

	<ul style="list-style-type: none"> This version can work on Galaxy software versions of all ages.
24-04-2015	2.15 <ul style="list-style-type: none"> E-13-02 could appear when used with robot interface.
16-01-2015	2.13 <ul style="list-style-type: none"> In language selection list all language names are in local, thus not translated. Soft ware upload more robust. Bug with error list on remote is fixed.
20-11-2014	2.12 <ul style="list-style-type: none"> Possibility for disabling sequence shift on torch trigger. E12-03 on remote is not seen any more.
29-09-2014	2.10 <ul style="list-style-type: none"> A gas calibration menu added, so with a correct calibration, the gas flow is correct. Remember that all wire feeders in the welding system must be calibrated. Error E26-01 is minimized. Job sequence is added. If torch is configured correct, jobs can be chosen with the torch potentiometer. Remember to assign a job index to the job that should be selected.
09-05-2014	2.09 <ul style="list-style-type: none"> MMA is working again.
29-04-2014	2.08 <ul style="list-style-type: none"> Older Galaxy software 10001321 will not be loaded on new Galaxy.
28-04-2014	2.07 <ul style="list-style-type: none"> Update via Remote² is possible now.
31-03-2014	1.06 (2.06) <ul style="list-style-type: none"> Works from Galaxy software 10001341 version 3.06
10-12-2013	1.05 <ul style="list-style-type: none"> Works from Galaxy software 10001341 version 3.05