



MIG MANAGER software history

10060001	Sigma-Galaxy-Flex 3000	E0
10060001	Flex 4000-5000	C0

Dato	MIG Manager 10060001
04-06-2010	<p>E0</p> <ul style="list-style-type: none"> Problem solved when showing strange messages in MigManager display.
30-10-2008	<p>D0</p> <ul style="list-style-type: none"> Communication speed is increased to 250kBaud. This version will work on: Flex 3000 Flex² 3000 Sigma² Galaxy <p>Will not work on: Flex 4000 Flex 5000</p>
29-06-2005	<p>C0</p> <ul style="list-style-type: none"> Communication speed is 125kBaud. This version will work on: Flex 4000 Flex 5000 <p>Will not work on: Flex 3000 Flex² 3000 Sigma² Galaxy</p>
23-06-2004	<p>B0</p> <ul style="list-style-type: none"> CAN messages for resetting MigManager is implemented.
01-01-2004	A0
Dato	MIG Manager 10060001
04-06-2010	<p>E0</p> <ul style="list-style-type: none"> Problem solved when showing strange messages in MigManager display.
30-10-2008	D0

MIG MANAGER software history

	<ul style="list-style-type: none">• Communication speed is increased to 250kBaud. This version will work on: Flex 3000 Flex² 3000 Sigma² Galaxy Will not work on: Flex 4000 Flex 5000
--	--